

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2017

Submitted Date:

06/28/2017

Document Number:

666803307

FIELD INSPECTION FORM

Loc ID 335083 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
 Name of Operator: VANGUARD OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277912	WELL	PR	11/01/2014	GW	045-10809	GUCCINI 41D-20-692	PR
277913	WELL	PR	06/07/2006	GW	045-10810	GUCCINI 41B-20-692	PR
277914	WELL	PR	06/07/2006	GW	045-10811	GUCCINI 31D-20-692	PR
277915	WELL	PR	06/05/2006	GW	045-10812	GUCCINI 31B-20-692	PR
290198	WELL	PR	04/17/2012	GW	045-14053	GUCCINI 31A-20-692	PR
290200	WELL	PR	04/17/2012	GW	045-14052	GUCCINI 41C-20-692	PR
290202	WELL	PR	09/05/2007	GW	045-14051	GUCCINI 31C-20-692	PR
290203	WELL	PR	09/05/2007	GW	045-14050	GUCCINI 41A-20-692	PR

General Comment:

2017 Flowline NTO Inspection 1000' Buffer
 Shared tank battery with facilities #418614

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume			corrective date
Type: Flow Line		#			
Comment:	In use; 8-2" steel risers at wellhead, 8-2", 16-3", 2-4" risers at separators				
Corrective Action:					Date:
Type: Horizontal Heated Separator		# 8			
Comment:	39.517008/-107.688522				
Corrective Action:					Date:
Type: Plunger Lift		# 8			
Comment:	39.517196/-107.687442				
Corrective Action:					Date:
Type: Ancillary equipment		# 3			
Comment:	Chemical unit at wellhead				
Corrective Action:					Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277912	Type:	WELL	API Number:	045-10809	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	277913	Type:	WELL	API Number:	045-10810	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	277914	Type:	WELL	API Number:	045-10811	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	277915	Type:	WELL	API Number:	045-10812	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	290198	Type:	WELL	API Number:	045-14053	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	290200	Type:	WELL	API Number:	045-14052	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	290202	Type:	WELL	API Number:	045-14051	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	290203	Type:	WELL	API Number:	045-14050	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Rip Rap	Pass			
		Check Dams	Pass			
Ditches	Pass					
Berms	Pass					
Gravel	Pass					
		Culverts	Pass			
Rip Rap	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401322526	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183262
666803314	NTO 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183259
666803315	NTO	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4183260