

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2017

Submitted Date:

06/28/2017

Document Number:

673404739**FIELD INSPECTION FORM**

Loc ID 391470 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 62300Name of Operator: NATIONAL COOP REFINERY ASSOCAddress: P O BOX 1404City: MCPHERSON State: KS Zip: 67460**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Floyd, James		jfloyd@acexploration.com	
Andrews, Dave		david.andrews@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Burger, Craig		craig.burger@state.co.us	

**General Comment:**

Inspector on location to witness removal of above ground dry hole marker and replacement with a plate at grade of hydraulic structure.

**COGCC Comments**

Comment	User	Date
Above ground marker was cut off. Surface casing was cut to water level and cement was chipped away to water level. New plate was welded on at water level. Casing debris and above ground marker were removed.	waldrone	06/28/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401324775	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184634</a>
673404740	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4184631</a>