

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2017

Submitted Date:

06/29/2017

Document Number:

673404724**FIELD INSPECTION FORM**
 Loc ID 324629 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10126Name of Operator: PARK ENERGY PETROLEUM LLCAddress: P O BOX 825City: WALDEN State: CO Zip: 80480**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
dalton, dan	307-871-2007	dndal1@aol.com	owner operator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212197	WELL	PR	05/01/2016	OW	057-06090	KUIPERS 1	SI

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted or information inaccurate on tanks or containers. No capacity on tank label.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/28/2017

Emergency Contact Number:			
Comment:	307-871-2007		
Corrective Action:		Date:	

Good Housekeeping:			
Type	OTHER		
Comment:	Oily waste in wooden box adjacent to not in use flowline.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	07/03/2017

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	2 unused 2" steel riser observed at 40.67731, -106.48328 and at wellhead not marked for abandonment or locked out tagged out. NTO Phase 1, Part 2: Any existing flowline or pipeline riser not in use must be clearly marked using fluorescent paint, have all operating valves removed and be capped (locked out/tagged out, bull plugged, or blind flange) until it can be cut-off below grade and sealed pursuant to Rule 1103 and the statewide Flowline NTO.		

Corrective Action:	Comply with Phase I-Part 2 of the May 2, 2107 Flowline NTO.		Date:	05/30/2017
Type: Flow Line	#			
Comment:	IN USE: 1 - 2" steel riser at tank. 1 - 2" steel riser at wellhead			
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1		STEEL AST		40.677430,-106.483410	
Comment:						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 212197 Type: WELL API Number: 057-06090 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDSComment:

Not pumping.
Review of monthly operations records indicate operator is delinquent in submitting
monthly operations reports.

Corrective Action: Submit required Form 7(s) to COGCCDate: 07/28/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent soil migration; erosion or soil movement.](#)

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401327796	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186556
673404749	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186550