

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/29/2017

Document Number:

673404742**FIELD INSPECTION FORM**Loc ID 397206 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|-------------------------------|---|
| Bennet, Waylon | | Waylon_Bennett@xtoenergy.com | XTO Integrity NTO contact |
| Dooling, Jessica | (970) 878-6800 | Jessica_Dooling@xtoenergy.com | Piceance Basin Field |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------------------|--------|-------------|------------|---------|----------------------------------|-------------|
| 451019 | GAS GATHERING SYSTEM | AC | 06/09/2017 | | - | 4-inch condensate - PCU2 to BSTB | EG |

General Comment:

Inspected FacilitiesFacility ID: 451019 Type: GAS API Number: - Status: AC Insp. Status: EG**Flowline**

| #1 | Type: Non-Well Site | of Lines | |
|----|---------------------|----------|--|
|----|---------------------|----------|--|

Flowline Description

Flowline Type: Non-Well Site Size: 4" Material: Carbon Steel
 Variance: No Age: Contents: Condensate

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted: Yes

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Line isolated at 39.86881, -108.28773 and 39.88703, -108.29462. Gauge at second coordinates. Line at 1 psi on arrival. Pressured up to 69.1 psi. At 5 minutes 69.1, at 10 minutes 67.3, at 15 minutes 66.8. Line contains flash condensate.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401327802 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186560 |
| 673404755 | Pressure test photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4186554 |