

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2017

Submitted Date:

06/30/2017

Document Number:

673404743**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field
Bennet, Waylon		Waylon_Bennett@xtoenergy.com	XTO Integrity NTO contact

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451231	GAS GATHERING SYSTEM	AC	06/27/2017		-	26-inch gas gathering line	EG

General Comment:

2017 Flowline NTO Inspection 1000' Buffer
Shadowing Operator Pressure Testing Team

Inspected FacilitiesFacility ID: 451231 Type: GAS API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Other Material: Carbon Steel
 Variance: No Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted: Yes

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Field wide shut-in. Line isolated and gauge placed at 39.93496, -108.29242, other end isolated at 39.86858, -108.28739. Unable to bleed down very much do to shut-in, normal operating pressure 100-120 psi. At 150psi started gauge recording, started test at 167.1 psi. at 5 min 166.3 psi, at 10 min 166.3 psi, at 15 min 166.3 psi.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401331064	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4189339
673404759	Pressure test photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4189329