

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2017

Submitted Date:

06/30/2017

Document Number:

673404745**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Waldron, Emily 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: PO BOX 6501City: ENGLEWOOD State: CO Zip: 80155**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field
Bennet, Waylon		Waylon_Bennett@xtoenergy.com	XTO Integrity NTO contact

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451234	GAS GATHERING SYSTEM	AC	06/27/2017		-	4-inch combined liquid flowline	EG

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer  
Shadowing Operator Pressure Testing Team

**Inspected Facilities**Facility ID: 451234 Type: GAS API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: 4" Material: Carbon Steel  
 Variance: Age: Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Yes Test Result: Charted: Yes

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Line isolated at 39.89295, -108.25124 and 39.88705, -108.29442 gauge placed at 39.89537, -108.25407. Attempted to pressure up to 50 psi but unable to because of isolation points location in line. Start test at 8.2 psi, at 5 min 7.8 psi, at 10 min 7.8 psi, at 15 min 7.9 psi. Unable to bleed off because of gauge position on line. No photos of gauge because of position of gauge.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401331067	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4189341">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4189341</a>