

COGCC Environmental Field Inspection Report Photo Attachment

Inspection Date: **June 30, 2017**

Steven J. Arauza, P.G.

COGCC Environmental Protection Specialist



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources
1120 Lincoln Street, Suite 801
Denver, CO 80203



Figure 1 - Pump jack and shed remain at abandoned well pad location.

P 303.894.2100 F 303.894.2109 www.colorado.gov/cogcc

Commissioners: John H. Benton - Acting Chair, Ashley L. Ager, Howard Boigon, James W. Hawkins,
Tommy Holton, Kent Jolley, Erin A. Overturf, Robert W. Randall, Dr. Larry Wolk

John W. Hickenlooper, Governor | Robert W. Randall, Executive Director, DNR | Matthew J. Lepore, Director





Figure 2 - Vertical heated separator remains on location.



Figure 3 - Crude oil ASTs remain on location. Tanks appear to be empty.



Figure 4 - Localized, stained soil at tank battery.



Figure 5 – Assorted debris (top photo - former shed and stairs; bottom photo – truck loadout containment device) located north of produced water pit.



Figure 6 - Oil skim tinhorn remains on location. Operator indicated that both pits would be remediated by 6/15/2017.



Figure 7 - Abandoned flowline risers N and NW of tinhorn.

COGCC Environmental Field Inspection Report Photo Attachment

Inspection Date: **June 30, 2017**

Steven J. Arauza, P.G.

COGCC Environmental Protection Specialist



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources
1120 Lincoln Street, Suite 801
Denver, CO 80203



Figure 8 - Produced water pit remains on location. Operator indicated that both pits would be remediated by 6/15/2017.