



Photo 1: View of the project area from the northeastern corner of the well pad facing center. Portions of the well pad are becoming revegetated with rubber rabbitbrush (*Chrysothamnus nauseosus*), western wheatgrass (*Pascopyrum smithii*), and crested wheatgrass (*Agropyron smithii*).



Photo 2: View of the wellhead facing center. What appears to be surface owner equipment is stored at the well head.



Photo 3: View of meter shed in the southwestern corner of the well pad.



Photo 4: View of the western portion of the project area from the northwestern corner facing southward. What appears to be surface owner equipment is being stored in the western portion of the well pad area.



Photo 5: View of area in the northwestern corner of the project area where diverted stormwater flows are directed down slope and it appears to be eroding the slope. Long term stormwater controls are needed in this area.



Photo 6: View of the western diversion within the project area, facing upstream from the northwestern corner.



Photo 7: View of what berm that appears to be functioning along the eastern edge of the well pad.



Photo 8: View of the eastern fill slope and vegetated area in the eastern portion of the project area, from the northeastern corner facing southward.