

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/29/2017

Submitted Date:

07/06/2017

Document Number:

685303448**FIELD INSPECTION FORM**Loc ID 334548 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 6301 DEAUVILLE BLVD

City: MIDLAND State: TX Zip: 79706

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

28 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pohl, April	505-333-1941	april.pohl@chevron.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216234	WELL	PR	08/23/1992	GW	067-07840	W ANIMAS-UNIVERSITY 9-1	PR
264265	WELL	PR	11/01/2002	GW	067-08741	WEST ANIMAS-UNIVERSITY 9-3	PR

General Comment:[2017 Flowline NTO Inspection Statewide](#)[Witnessing Flowline Abandonment](#)[See link at end of report for path to downloadable pictures.](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel two track road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Stand alone framed metal sign located at wellhead.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tank. NFPA label is currently on tank side wall and is not visible from outside berms. Signage needs to be moved so it is visible outside containment berms to comply with Rule 210 requirement that marking be in a conspicuous place.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Operator contact information posted on wellhead sign.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	LOCATION		
Comment:	6' Chainlink fencing with 3 strands of barbwire.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 8		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	Not in use - 3" poly line on NW corner of location 37.13035/-107.51509. Line was laid for future use and never used. Line leaves location and comes above ground at 37.11496/-107.52492. Just past mile marker 11 on CR 213. Line being abandoned.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:	Wellhead.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	In use - 3" steel line from wellhead casing to separator inlet. All points on location. 37.217729/-107.858286 from scout card.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Electrical service equipment.		Date:	
Corrective Action:			Date:	
Type: Pig Station	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 2			
Comment:	Electric motor.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	In use - 6" steel line from separator outlet to gas meter inlet. All points on location. 37.217729/-107.858286 from scout card.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	In use - 2" steel line from wellhead tubing to water line tie in for 9-1 and to separator inlet. All points on location. 37.217639/-107.858237 from scout card.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Vertical rod pump.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	In use - 2" steel line from wellhead tubing to water line tie in at 9-3 and to separator inlet. All points on location. 37.217729/-107.858286 from scout card.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Telemetry equipment.		Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Chemical tank and pump on spill prevention.		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:	In use - 6" steel line from separator outlet to gas meter inlet. All points on location. 37.217639/-107.858237 from scout card.		Date:	
Corrective Action:			Date:	

Type: Flow Line	# 1	
Comment:	In use - 6" steel line from wellhead casing to separator inlet. All points on location. 37.217639/-107.858237 from scout card.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:	Steel open top tank with expanded metal top in pit with earthen berms.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 216234 Type: WELL API Number: 067-07840 Status: PR Insp. Status: PR**Producing Well**Comment: PR - Review of electronic well file indicates last reported production as April 2017.

Corrective Action:

Date:

Flowline

#1 Type: Well Site

1 of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 3"Material: Poly

Variance:

Age:

Contents: Other**Integrity Summary**

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: Yes

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☒ 1103. Abandonment

Comment: 3" poly line on NW corner of location (A) 37.13035/-107.51509. Line was laid for future use and never used. Line leaves location and comes above ground at (B) 37.11496/-107.52492 (Just past mile marker 11 on CR 213, access road on left with risers and valves on corner). Line was cut off below grade on both ends and capped.

Corrective Action:

Date:

Facility ID: 264265 Type: WELL API Number: 067-08741 Status: PR Insp. Status: PR**Producing Well**Comment: PR - Review of electronic well file record indicates last reported production as April 2017.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: [Location off CR 213 above Animas river in commercial/residential area.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			Chemical tank on spill prevention.
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tank.

Comment: Stormwater BMPs appear to be functioning at time of inspection.Corrective Action: Date: Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401333448	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191102
685303462	(B) Point riser before excavation and cut off.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191080
685303463	(A) Point cut and capped.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191081
685303464	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191082
685303465	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191083
685303466	Tank with signage not visible above berms.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191084
685303467	Tank signage at approach to tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191085