

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/30/2017

Submitted Date:

07/06/2017

Document Number:

685303449

FIELD INSPECTION FORM

Loc ID 306898 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES, INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275103	WELL	PR	08/12/2014	GW	067-08998	CORY JACK 33-7-11 2	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)
[Good Housekeeping \(Weeds\) follow up inspection. All open corrective actions from previous inspection are still applicable.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

WEEDS

Comment: Corrective action completed.

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 275103 Type: WELL API Number: 067-08998 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well currently SI to comply with 2017 Flowline NTO Inspection. Failed supply gas line pressure test.

Corrective Action: Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401333449	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191103
685303468	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191086
685303469	View towards wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191087
685303470	View towards separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191088
685303471	View towards meter house.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191089
685303472	View towards chemical tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4191090