

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/13/2017

Submitted Date:

07/13/2017

Document Number:

687400092

FIELD INSPECTION FORM

Loc ID 319856 Inspector Name: Kraich, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 27635
Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH CO
Address: PO BOX 1896
City: EDWARDS State: CO Zip: 81632

Findings:

- 18 Number of Comments
- 11 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Hickey, Mike		mike.hickey@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Rutter, Jenn		JRutter@adcogov.org	Unincrop. Adams County Inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201602	WELL	PR	02/19/2015	OW	001-07005	NORTH COLORADO BLVD 1	PR

General Comment:

[Within 1000' of dwelling.](#)

Location			
Lease Road:			
Type	Access		
comment:	Road is shared and maintained by great western battery.		
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	All signs have out of order emergency contact information. See Photos	Date:	08/14/2017
Corrective Action:	Install sign to comply with Rule 210.b.		
Good Housekeeping:			
Type	WEEDS		
Comment:	Severely overgrown weeds through location, see photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	07/23/2017
Type	OTHER		
Comment:	Stained soil around wellhead and production tanks.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	08/14/2017
Type	UNUSED EQUIPMENT		
Comment:	Unused tubing stored on location. See photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	10/13/2017
Type	DEBRIS		
Comment:	Debris is spread throughout location around separator and tank battery, see photos.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/14/2017
Type	TRASH		
Comment:	Trash stored inside of shed on location, see photos		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/14/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Privacy fence around location, is in disrepair.		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Electric motor		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment: Conventional unit		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		
Comment:	Produced water tank has no signage or placarding, see photos				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 08/14/2017

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Weeds have overgrown in and around berm. See Photo			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date: 07/23/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:	Rear water drain valve appears to be leaking. See Photos				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 08/14/2017

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment: Berms are overgrown with weeds, see photos					
Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.				Date:	<u>07/23/2017</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201602 Type: WELL API Number: 001-07005 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Reords indicate shut in status as of 9/2014, no reporting since 2/2015.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan. Date: 07/23/2017

COGCC Comments

Comment	User	Date
Surface equipment, and location are in serious disrepair, well and battery are located in close proximity to several residences.	kraicha	07/13/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400093	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4197419