

Location

Lease Road:			
Type	Access		
comment:	Access wellhead through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by main access road		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wire fence around wellhead		
Corrective Action:		Date:	

Equipment:			
Type:	Plunger Lift	# 0	corrective date
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 254138 Type: WELL API Number: 125-08016 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(ODELL 21-7, 32-7, SHAY 11-7, 22-7\) 1840' SE @ 39.899260/-102.229430](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401335178	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4192498