



**Photo 1: View of the northern portion of the project area from the northeastern corner facing westward.**



**Photo 2: View of the southern portion of the project area from the southeastern edge facing westward.**



**Photo 3: View of liner debris within the eastern portion of the project area.**



**Photo 4: View of musk thistles (*Carduus nutans*) growing within the cobble run-down at the entrance to the well pad.**