

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2017

Submitted Date:

07/11/2017

Document Number:

674603450**FIELD INSPECTION FORM**
 Loc ID 320302 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10474Name of Operator: MENDELL FINISTERRE II LLCAddress: 1750 N HUMBOLDT ST #201City: DENVER State: CO Zip: 80218**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
AYLING, ROB	619-988-0828	rayling@mendellenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203410	WELL	SI	03/01/2017	OW	001-08919	ELMS 2	EG

General Comment:

Engineering Integrity Inspection (Flowline Abandonment) performed on June 28th, 2017 in response to form 42 Doc #401313710 received by COGCC on 06/20/2017 that outlines: Flowlines abandoned per Rule 1103. Details of observations made during this field inspection are available in the comment section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 203410 Type: WELL API Number: 001-08919 Status: SI Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: [Flowlines associated with the Elms#2 have been removed and/ or abandoned in place. Form 42 Doc #401313710 received by COGCC on 06/20/2017.](#)

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
Comments from Previous EG Inspection Doc #674603288 performed on 04/12/2017:	maclarej	07/11/2017
COGCC integrity inspector met with Mendell Energy's senior engineer Bill Davis on location and discussed plans for flowline removal abandonment. Excavation and remediation activities associated with the produced water vault were observed in progress. There were several un-marked historical abandoned flowlines encountered during the excavation/ remediation project. These flowlines are being removed. The dump lines associated with the facility are being removed. The well site flowline(s) routed on location from the Elms 2 and Tudex Rheinholt NC4 (API 001-09365) are scheduled to be partially removed and/ or abandoned in place per 1103. An existing Tudex Petroleum flowline (from Sevens 1/ API 001-07939) runs adjacent to the East side of the excavation/ location is being left in place (risers in valve can).		
Note: There are (2) flowline valve set risers (1" and 2") associated with Tudex Petroleum operations (inside/ protected by a metal culvert) located adjacent to/ just off of the NE corner of this location.	maclarej	07/11/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401337309	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194292
674603453	Flowline risers in valve can; Other operator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194288
674603454	View of re-contoured location; looking south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4194289