

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 1: Some stained soil has been remediated**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 2: Stained soil on pit**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 3: Stained soil on pit**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 4: Marked deadman**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 5: Stained soil at fiberglass skim**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 6: Stained soil at produced water tank**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 7: Inadequate berms at produced water tank**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo from prior inspection for comparison**



**Photo 8: Production tank properly placarded**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo 9: Stained soil, debris inside treater house**



**Photo 10: Stained soil at vertical separator**

**Inspection Photos**  
**Location Name: DOC Showers #32-12-10**  
**API: 05-123-19437**



**Photo 11: Disconnected risers at crude oil tanks**