



Photo 1: View of riser at 37.64415, -108.77412, at entrance to access road.



Photo 2: View of the beginning of access road facing toward the well pad (westward). Vegetation is sparse and does not appear sufficiently reclaimed.



Photo 3: View of the eastern edge of the well pad facing northward.



Photo 4: View of the project area from the southeastern corner facing center.



Photo 5: View of hay production within the well pad area. Production is significantly less than reference area (Photo 6). This is an indication that reclamation on the well pad may not be sufficient. A future vegetation assessment will be conducted.



Photo 6: View of hay production outside and adjacent to the project area in the reference area. Hay production is significantly higher than within the project area.