



Photo 1: View of riser at 37.63271, -108.77362, at entrance to access road. Riser is tagged with DO NOT OPERATE sign.



Photo 2: View of a second riser at 37.63208, -108.77241. This riser appears to be associated with the former well and is not locked or tagged out.



Photo 3: View of wellhead and other metal debris in southern portion of the project area.



Photo 4: View of the project area from the southeastern corner facing center.



Photo 5: View of the southern portion of the former well pad surface with poor revegetation.



Photo 6: View of the eastern portion of the project area from the southeastern corner facing northwestward. Large areas with little to no vegetation remain. Surrounding cropland vegetation in background.