

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/10/2017

Submitted Date:

07/12/2017

Document Number:

680601753

**FIELD INSPECTION FORM**

Loc ID 326095 Inspector Name: ROY, CATHERINE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone | Email               | Comment                         |
|--------------|-------|---------------------|---------------------------------|
| Beebe, Sabre |       | Sabre.Beebe@bp.com  | <a href="#">All Inspections</a> |
| ,            |       | SanJuanCOGCC@bp.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 215859      | WELL | PR     | 05/30/1990  | GW         | 067-07464 | THOMAS JACQUEZ B 1 | RI          |

**General Comment:**

[This is an interim reclamation and stormwater inspection, as well as followup inspection for 667100457 conducted on April 13, 2015.](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: 08/11/2017

Overall Good:

| <b>Spills:</b> |      |        |  |  |
|----------------|------|--------|--|--|
| Type           | Area | Volume |  |  |
|                |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 215859 Type: WELL API Number: 067-07464 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by pinion juniper woodland and grassland, as well as semi-rural rangeland. Corrective action described in 2015 inspection, to reclaim unnecessary road has been addressed. Portion of unnecessary road leading off of the western edge of the well pad is closed and revegetated. See attached photos.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment

Corrective Action  Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action  Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment

Corrective Action  Date \_\_\_\_\_



| <b>Storm Water:</b>   |                 |                         |                       |               |                          |         |
|---|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|   |                 |                         |                       |               |                          |         |
| Comment: <input type="text" value="Stormwater erosion appears to be controlled on the location at this time."/> |                 |                         |                       |               |                          |         |
| Corrective Action: <input type="text"/>   |                 |                         |                       |               | Date: _____              |         |
| <b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT                                   |                 |                         |                       |               |                          |         |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401338597    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195339">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195339</a> |
| 680601754    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195338">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4195338</a> |