

Inspection Photos
Location Name: Showers #5-4
API: 05-123-19939



Photo from prior inspection for comparison



Photo 1: Unused production tank



Inspection Photos
Location Name: Showers #5-4
API: 05-123-19939



Photo from prior inspection for comparison



Photo 2: Stained soil at housing, exhaust

Inspection Photos
Location Name: Showers #5-4
API: 05-123-19939



Photo from prior inspection for comparison



Photo 3: Stained soil at pump jack

Inspection Photos
Location Name: Showers #5-4
API: 05-123-19939



Photo from prior inspection for comparison



Photo 1: Stained soil at wellhead. TA well. Bradenhead not plumbed to surface.