



*Photo 1- Wellhead sign, wellhead, and pumping unit.*





*Photo 2 – Localized, oil stains on wellhead equipment, note COGCC tag with instructions not to operate remains attached.*





*Photo 3 - Weed growth at separator.*



*Photos 4 & 5- Tank battery with earthen berm, note fluorescent paint on abandoned flowline riser beside crude oil AST (top).*





*Photo 6 - Abandoned flowline riser, painted and tagged to comply with Flowline NTO.*

COGCC Environmental Field Inspection Report Photo Attachment

Inspection Date: July 18, 2017

Steven J. Arauza, P.G.

COGCC Environmental Protection Specialist



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources  
1120 Lincoln Street, Suite 801  
Denver, CO 80203



*Photo 7 – Frac tank and pipe trailer north of pump jack.*