

COGCC Environmental Field Inspection Report Photo Attachment

Inspection Date: **July 18, 2017**

Steven J. Arauza, P.G.

COGCC Environmental Protection Specialist



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources
1120 Lincoln Street, Suite 801
Denver, CO 80203



Figure 1 – Oil-stained soil, uncapped equipment, and flowline risers at wellhead. Note: Trailer, electrical boxes, and additional junk in background.

P 303.894.2100 F 303.894.2109 www.colorado.gov/cogcc

Commissioners: John H. Benton - Acting Chair, Ashley L. Ager, Howard Boigon, James W. Hawkins,
Tommy Holton, Kent Jolley, Erin A. Overturf, Robert W. Randall, Dr. Larry Wolk

John W. Hickenlooper, Governor | Robert W. Randall, Executive Director, DNR | Matthew J. Lepore, Director





Figure 2 - COGCC emergency contact information affixed to electrical control panel.



Figure 3 - Electrical boxes, transformers, ammonia tank, motor oil bucket, and metal panel (debris) southwest of pumping unit.



Figure 4 - Abandoned flowline risers (top) and unused pipe (bottom) at former tank battery.