

July 20, 2017 COGCC Environmental Field Inspection of DIVERSIFIED ENERGY LLC (Diversified)  
Bingham Location ID: 313094.



Location sign.



View looking up lease road (recent grading).



Plastic liner incorporated in recent grading throughout lease road.



throughout lease road.

Plastic liner incorporated in recent grading



dirt work.

Plastic liner incorporated in tank berm from recent



dirt work.

Plastic liner incorporated in tank berm from recent



dirt work.

Plastic liner incorporated in tank berm from recent



Treatment area.

Plastic liner incorporated in material in former Land



Treatment area.

Plastic liner incorporated in material in former Land



treatment area.

Appears to be oily stained material in former Land



Former Land treatment area (plastic liner pieces).



Former Land treatment area (plastic liner pieces).



Material appears to be pushed off of Location.



Plastic liner in material pushed off of Location.



Looking east across Location.



Bingham 1-14 well (vegetation).



Plastic liner incorporated in recent grading throughout lease road.



Appears to be oily material (hydrocarbon odor present) and plastic liner in recent grading on lease road.