

On July 20, 2017 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of DIVERSIFIED ENERGY LLC (Diversified) J.P. Weise # 1 Location ID: 312773. The INSP included Pit Facility 284545, the well (API 05-081-05289), and tank battery area. Weather was sunny to partially cloudy and temperature app mid 60s degree F and wind from the south. Well was not producing at time of inspection. *For the most recent Field and Environmental Field inspection report of this facility, please refer to document #685100081. At the time of the inspection, corrective actions (CAs) provided in that inspection had not been addressed. The overall inspection status shall remain the same as that document until all CAs have been completed.* The following is a summary:

Well head:

Valve at well was in closed and locked position.
Oil staining was covered with material such as gravel.
Vegetation (weeds) growth around pump jack

Tank Battery:

Five (5) 400 bbl tanks present. Tanks have marking that indicate Weise 1B (77824), Urie 1B (77456), 1B (77825), U-1, and U-2. Tank battery is bermed with Vegetation (weeds) throughout. Oily stains on ground surface beneath valves, fittings, and hammer unions covered with material such as grave..

Pit Facility ID 284545:

An app 40' x 30' x 8' deep pit was observed. Livestock/wildlife tracks were noted throughout pit. Oily residue was noted in the pit. Vegetation (weeds) along the berms of the pit. Hydrocarbon odor was noted downwind of the pit.

Location:

Vegetation (weeds) growth across Location.

Corrective Actions (CAs):

Address the CAs outlined in the previous Inspection Report, Document Number 685100081.

By August 4, 2017 Comply with Rule 603.f using the Rule 603.f guidance document for further details. (Including the management of weeds).

By July 26, 2017 remediate the oily stains on Location, beneath valves, fittings, and unions at well head and tanks. Properly treat or dispose of oily waste in accordance with Rule 907.e.