



**photo 1:** Facing southwest along the access road.



**photo 2:** Facing southwest along the access road toward the location.





**photo 3:** Facing southwest along the access road toward the location.



**photo 4:** Facing southwest toward the location.





**photo 5:** Northwest corner of the location facing southeast.



**photo 6:** There is List B noxious weeds (Bull thistle) at the northwest side of the location.





**photo 7:** Southwest side of the location facing northeast.



**photo 8:** There is List B noxious weeds (Canada thistle) at the southwest side of the location.





**photo 9:** There is subsidence occurring along the south side where soil was placed into the cut slope.



**photo 10:** Southeast side of the location facing northwest.





**photo 11:** Northeast side of the location facing southwest.,



**photo 12:** Facing east toward the surrounding undisturbed area.