

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2017

Submitted Date:

07/25/2017

Document Number:

688000037**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 59100Name of Operator: MONAHAN* REX FAMILY TRUSTAddress: P O BOX 1231City: STERLING State: CO Zip: 80751**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Aaron		aaron.trujillo@state.co.us	
Melissa, Rob		jankovsky@comcast.net	
Ramos, Martha		martha.ramos@state.co.us	
Fiscus, Joann		fiscus3@kci.net	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117501	PIT				-	LARSEN 1-A	EI

General Comment:

Environmental inspection related to bond release request. Subsidence is evident in the former pit area and agricultural production is not evident. The location must pass a final reclamation inspection prior to closure of the Pit Facility and subsequent bond release.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 117501Lat: 39.962509Long: -103.572946Reference Point: SEOther: Length: 130Width: 90**Lining:**

Liner Type:

Liner Condition:

Comment:

Pit has been backfilled, subsidence of the backfill material is evident, location is not supporting agricultural production.

Corrective Action

Comply with Rule 1004 regarding production pit closure.

Date: 08/31/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000038	Location Photographs 7-17-2017	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4206838
688000039	Historic Aerial Photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4206839