

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2017

Submitted Date:

07/18/2017

Document Number:

679902774**FIELD INSPECTION FORM**
 Loc ID 303057 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 24320Name of Operator: DIAMOND OPERATING, INC.Address: 6666 GUNPARK DR STE #200City: BOULDER State: CO Zip: 80301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Dave	303-494-4420	davep@flatironenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252360	WELL	PR	02/01/2013	GW	125-06233	HAYS-CANTRALL 1-12	PR

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	Two track through pasture			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Lease sign mounted to meter shed			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Stencil on water tank			
Corrective Action:	Add NFPA label. Install sign to comply with Rule 210.b.			Date: 09/18/2017
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds in fence around water tank, meter shed and wellhead			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Wire fence around wellhead, water tank and meter shed			
Corrective Action:				Date:
Equipment:				
Type: Deadman # & Marked			# 4	corrective date
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run			# 1	
Comment:			Meter run in metal shed	
Corrective Action:				Date:
Type: Vertical Separator			# 2	
Comment:			1-Vertical gas separator in metal shed 1-Vertical gas separator 50% buried by metal shed	

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.893140,-102.244400	
Comment:	Fiberglass water tank 50% buried					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)	150bbbls				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	252360	Type:	WELL	API Number:	125-06233	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Access has erosion west of Hays-Cantrall 43-12. Erosion on access needs repaired and maintained to make it passable](#)

Corrective Action: [Repair and maintain access to location](#)

Date: 08/18/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401347324	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4201541