

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: 2 (mph) Direction From: West Weather: Partly Temperature: 95 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Other

Comment: Open 20in casing 15ft tall on well that was P&A in 1925. Indication of a leak was found during FLIR survey.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680200076	North Fruita	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4208200