

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2017

Submitted Date:

07/20/2017

Document Number:

666803372**FIELD INSPECTION FORM**Loc ID 334836 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211341	WELL	PR	11/04/1996	GW	045-07101	DUNN 32-16	PR
268636	WELL	PR	02/08/2004	GW	045-09278	SHIDELER 32-9D (P32)	PR
268637	WELL	PR	02/01/2011	GW	045-09279	SHIDELER 32-10D (P32)	SI
268668	WELL	PR	02/01/2011	GW	045-09284	SHIDELER 32-9C (P32)	SI
274896	WELL	PR	10/29/2004	GW	045-13422	DUNN 32-16D (P32)	PR
274897	WELL	PR	01/22/2005	GW	045-13421	DUNN 5-7D (P32)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

6

Comment:

Corrective Action:

Date:

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		39.478943,-107.684849
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	Centralized battery				

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 211341 Type: WELL API Number: 045-07101 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 268636 Type: WELL API Number: 045-09278 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 268637 Type: WELL API Number: 045-09279 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last posted production numbers Sept 2016

Corrective Action:

Date: _____

Facility ID: 268668 Type: WELL API Number: 045-09284 Status: PR Insp. Status: SI

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Last posted production numbers Sept 2016

Corrective Action:

Date: _____

Facility ID: 274896 Type: WELL API Number: 045-13422 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 274897 Type: WELL API Number: 045-13421 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			
Berms	Pass					
Gravel	Pass					
Seeding	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401349420	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4202922