

Inspection Photos
Location Name: Roy Dutcher 2
API: 05-123-08945



Photo from prior inspection for comparison



Photo 1: Stained soil removed

Inspection Photos
Location Name: George Gerhardt 2
API: 05-123-08124



Photo 2: Wellhead sign unreadable

