

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2017

Submitted Date:

07/21/2017

Document Number:

674901818**FIELD INSPECTION FORM**Loc ID 333980 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268611	WELL	PR	03/01/2011	GW	067-08831	KLUSMAN RANCHES 2	EI
299154	WELL	PR	02/23/2011	GW	067-09640	KLUSMAN RANCHES 4	EI

**General Comment:**

On July 19, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Klusman Ranches #2 and #4. For the most recent field inspection report of this facility, please refer to document #685301975.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Free standing signs near PBVs. Labels and placards on PBVs.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

<b>Good Housekeeping:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Stock panel fencing around all equipment on location.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel fencing around well heads.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Electric pump jack on Klusman Ranches #4.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Linear rod pump on Klusman Ranches #2.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.122531,-107.683318
Comment:	Double walled PBV.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	95 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.122812,-107.682578
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity) 95 bbl.	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>268611</u>	Type:	<u>WELL</u>	API Number:	<u>067-08831</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>299154</u>	Type:	<u>WELL</u>	API Number:	<u>067-09640</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			
Waddles	Pass					
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On July 19, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Klusman Ranches #2 and #4. For the most recent field inspection report of this facility, please refer to document #685301975.	hughesj	07/21/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401350705	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204110</a>
674901819	Klusman Ranches #2 PW PBV.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204106">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204106</a>
674901820	Klusman Ranches #4 double walled PW PBV.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204107">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204107</a>
674901821	Klusman Ranches #2 well head.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204108">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204108</a>
674901822	Klusman Ranches #4 pump jack and well head.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204109">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4204109</a>