

Inspection Photos

7/27/2017

Operator: PETRO-CANADA RESOURCES (USA) INC -
72085

Location ID: 311698

Inspection Doc. Number: 675103759

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 311698



Photo 1: Photo taken from the south side of the drainage, adjacent to the pit and well location, facing north. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details.



Photo 2: Photo taken from the south side of the drainage, adjacent to the pit and well location, facing northwest. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details.

Inspection Photos

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 311698



Photo 3: Photo taken from the north side of the drainage, adjacent to the pit and well location, facing south. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details.



Photo 4: Photo taken from the north side of the drainage, adjacent to the pit and well location, facing southwest. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details.

Inspection Photos

Operator: PETRO-CANADA RESOURCES (USA) INC - 72085

Location ID: 311698



Photo 5: Photo taken from the north side of the drainage, adjacent to the pit and well location, facing west. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details.



Photo 6: Photo taken from within the drainage, west of the well/pits, facing east. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details. Hat indicated by yellow arrow used for reference.



Photo 7: Photo taken from within the drainage, west of the well/pits, facing east. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details. Hat indicated by yellow arrow used for reference.



Photo 8: Photo taken from within the drainage, west of the well/pits, facing east. Photo shows area of degradation that remain un-stabilized. Further degradation since previous inspection evident. See photos from inspection doc. # 682500927 for additional details.