

Inspection Photos

7/27/2017

Operator: PETRO-CANADA RESOURCES (USA) INC -
72085

Location ID: 311664

Inspection Doc. Number: 675103763

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 1: Photo taken from the northern disturbance area, facing northwest. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed. Straw wattles observed in photo appear to be same wattles from previous inspections up to and over a year ago. BMPs in disrepair and is now debris.



Photo 2: Photo taken from the northern disturbance area, facing west. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed. Straw wattles observed in photo appear to be same wattles from previous inspections up to and over a year ago. BMPs in disrepair and is now debris.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 3: Photo taken from the northern disturbance area, facing north. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed. Straw wattles observed in photo appear to be same wattles from previous inspections up to and over a year ago. BMPs in disrepair and is now debris.



Photo 4: Photo taken from the northern disturbance area, facing west. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed. Straw wattles observed in photo appear to be same wattles from previous inspections up to and over a year ago. BMPs in disrepair and is now debris.



Photo 5: Photo taken from the down slope on the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed.



Photo 6: Photo taken from the down slope on the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 7: to taken from the down slope on the northern disturbance area, facing east towards the access road. Photo shows erosion has not been stabilized, not BMPs have been installed and/or maintained. No evidence of any additional remediation or reclamation efforts observed.



Photo 8: to taken from the down slope on the southern disturbance area, facing east towards the access road. Photo shows areas of the disturbance that remain un-vegetated and un-stabilized. No evidence of any additional remediation or reclamation efforts observed.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 9: Photo taken from the down slope on the southern disturbance area, facing east towards the access road. Photo shows areas of the disturbance that remain un-vegetated and un-stabilized. No evidence of any additional remediation or reclamation efforts observed.



Photo 10: Photo taken from the down slope on the southern disturbance area, facing east towards the access road. Photo shows areas of the disturbance that remain un-vegetated and un-stabilized. No evidence of any additional remediation or reclamation efforts observed.

Inspection Photos
Operator: PETRO-CANADA RESOURCES (USA) INC - 72085
Location ID: 311664



Photo 11: Photo taken from the fenced remediation area. Photo shows areas of the remediation area that remain bare and exposed soil. No evidence of any additional remediation or reclamation efforts observed.



Photo 12: Photo taken from the fenced remediation area. Photo shows areas of the remediation area that remain bare and exposed soil. No evidence of any additional remediation or reclamation efforts observed.