

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

684903970**FIELD INSPECTION FORM**
 Loc ID 318870 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10542Name of Operator: CUB CREEK ENERGYAddress: 200 PLAZA DRIVE SUITE 100City: HIGHLANDS State: CO Zip: 80129**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gardner, Bob		bob.gardner@cub-creek.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	
Baily, Scott		scott.baily@cub-creek.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445614	WELL	DG	03/25/2017		123-43128	Haley 9HZ	WO

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Treated with magnesium chloride		
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Sound walls, all sides		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 445614 Type: WELL API Number: 123-43128 Status: DG Insp. Status: WO**Complaint**Comment: Complaint #: 200443384Field Inspector Assigned: C PesickaWell Number: 05- Location #: 318870Inspection Document #: 684903970Nature of complaint: Sound, DustIf Sound GPS Coordinates of Survey Location: n/aInspection Observations:

An inspection of the above location was conducted on 08/01/17. Spoke with Liberty personnel on site, who informed the inspector that the site had concluded its hydraulic fracturing treatment, and the site was being rigged down. As the complaint was submitted during active fracturing activity on 07/31/17, no sound study was conducted. Inspector noted that county road access was treated with magnesium chloride, with no fugitive dust observed.

18A doc#: 200443395

Corrective Action:

Date:

Well StimulationStimulation Company: LibertyStimulation Type: HYDRAULIC FRAC**Observation:**

Other: _____

Maximum Casing Recorded: _____ PSI

Tubing: _____

Surface: _____

Intermediate: _____

Production: _____

Instantaneous Shut-In Pressure (ISIP) _____

Bradenhead Psi: _____

Frac Flow Back: Fluid: _____ Gas: _____

Comment: Hydraulic Fracturing treatment concluded. Site is being rigged down.

Corrective Action:

Date: _____