

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2017

Submitted Date:

07/25/2017

Document Number:

679700564**FIELD INSPECTION FORM**

Loc ID 330865 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Regulatory, Foundation		regulatory@foundationenergy.com	<a href="#">Regulatory Email</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
199860	WELL	PR	08/10/1999	OW	123-19794	State 36-3-9	EI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Sign has not been repaired/revised as requested on inspection #684903385		
Corrective Action:	Install sign to comply with Rule 210	Date:	05/30/2017

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused rod adjacent pumpjack		
Corrective Action:	Comply with Rule 603.f. using Rule 603.f. guidance document for further details	Date:	02/18/2017

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			
Crude Oil	WELLHEAD	<= 1 bbl			
Comment:	crude oil stained soil around wellhead				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date:	08/24/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	appears adequate		
Corrective Action:		Date:	
Type	PIT		
Comment:	appears adequate		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Numerous animal burrows in containment berms				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).				Date: 09/09/2016

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: 40.450270Long: -104.156180Reference Point: SEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: No Pit Permit has been submitted. No approved pit permit from previous operator has been locatedCorrective Action: Submit an eForm 15 Pit Report to update COGCC records with current information.Date: 08/29/2016**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401354032	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207735">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207735</a>
679700573	Oil staining at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207728">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207728</a>
679700574	Crude oil ASTs and sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207729</a>
679700575	Pit from southwest corner	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207730">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207730</a>
679700576	burrows in containment berm	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207731">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4207731</a>