

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2017

Submitted Date:

08/02/2017

Document Number:

674901835**FIELD INSPECTION FORM**

Loc ID 325654	Inspector Name: Hughes, Jim	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10000</u> Name of Operator: <u>BP AMERICA PRODUCTION COMPANY</u> Address: <u>380 AIRPORT RD</u> City: <u>DURANGO</u> State: <u>CO</u> Zip: <u>81303</u>				<b>Findings:</b> <u>16</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215173	WELL	PR	12/21/1988	GW	067-06778	EVELYN PAYNE A 1	EI

**General Comment:**

On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Evelyn Payne A #1. For the most recent field inspection report for this facility, please refer to document #674901299.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	CONTAINERS			
Comment:	Lube oil container is labeled "Mobil Pegasus 1 Oil".			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	21 bbl. PBV has label and placard.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on well head sign.			
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
Lube Oil	WELLHEAD	<= 1 bbl		
Comment:	Stained gravel around well head and Oil lift equipment.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date: 09/04/2017
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	TANK BATTERY			
Comment:	Stock panel fencing around PBV.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Stock panel fencing around well head and Oil lift equipment.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Ancillary equipment	# 1			corrective date
Comment:	Oil lift pump controller. Stained soil near equipment.			
Corrective Action:				Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:	Stained soil near wellhead, equipment is wet.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.261369,-107.555048	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 bbl.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	In Process	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Erosion along eastern edge of location.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Evelyn Payne A #1. For the most recent field inspection report for this facility, please refer to document #674901299. Corrective actions required by that inspection have either not been addressed or have reoccurred. Stained gravel near the Oil Lift equipment and well head were observed during this field inspection. Erosional channels were observed along the eastern edge of the location.	hughesj	08/02/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901836	Stained soil near well head, wet equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214862">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214862</a>
674901837	Stained gravel near Oil Lift equipment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214863">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214863</a>
674901838	Erosion along eastern edge of location.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214864">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214864</a>