

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/07/2017

Submitted Date:

08/04/2017

Document Number:

679100103**FIELD INSPECTION FORM**
 Loc ID 312997 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num:
Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 10525Name of Operator: SANTA FE NATURAL RESOURCES INCAddress: 4833 FRONT STREET UNIT B 506City: CASTLE ROCK State: CO Zip: 80104**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Michael Sullivan MICHAEL		durangopl@earthlink.net	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:

Date of Inspection: 06-07-17

Type of Inspection: Containment, Stormwater, Fracing

Location Name: McIntyre 1-3R Pad; McIntyre 1-3ST Well;

Location ID #: 312997

API #: 05-081-06608

Observed site stormwater/erosion control and attempted frac on 06-07-17; site is partially reclaimed with natural vegetation; some weeds present; minor evidence of soil staining around wellhead; tank has secondary containment and adequate signage; stormwater/erosion controls are adequate - no indication of offsite migration of fluids or sediment from well pad; operator attempted to complete two stages of the frac, however during pressure up after setting packer, pressures dropped almost immediately; operator indicated there were issues with the production casing and would need to abort the frac and abandon the lateral; operator indicated that they would sundry a report of the work attempted and done.