

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2017

Submitted Date:

07/31/2017

Document Number:

673715881

**FIELD INSPECTION FORM**

Loc ID 437633 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10492  
Name of Operator: AGAVE OIL & GAS LLC  
Address: 201 PECAN STREET #100  
City: FORT WORTH State: TX Zip: 76102

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Henninger, Rick	(903) 271-0656	rick@agaveoilandgas.com	
Holcomb, Jim		jim@agaveoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437636	WELL	WO	05/01/2017	LO	039-06677	Haas 1-29	WO

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	817-946-6860	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Prime Mover	# 1		
Comment:	propane tank		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Two combustors are not 75' from wellhead. Operator was contacted, the well was SI right away and combustors will be moved.		
Corrective Action:	Move equipment to comply with minimum 75 foot setback as per Rule 605.b.(4).	Date:	09/01/2017

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		
Comment:	frac tank, 2 other empty frac tanks on location				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	skirt		
Corrective Action:		Date:	
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 437636 Type: WELL API Number: 039-06677 Status: WO Insp. Status: WO**Completion**Operation: FlowbackDate Flowback: 06/17/2017

Contractor:

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401360404	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4212823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4212823</a>
673715884	Agave Haas 1-29 flowback	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4212822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4212822</a>