



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner of the well pad facing southward. Areas documented from previous inspections are reclaimed.



Photo 3: Another view of reclamation area in the western portion of the project area. Scattered musk thistles in the project area should be controlled by the operator of the producing wells.



Photo 4: Erosion is continuing along the western edge of the project area and should be controlled by the operator of producing wells.