

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2017

Submitted Date:

08/07/2017

Document Number:

679100113**FIELD INSPECTION FORM**

Loc ID 311896 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Nolan Redmon		nredmond@catamountep.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:Date of Inspection: 7-27-17Type of Inspection: Wildlife Consultation, Containment, StormwaterLocation Name: Herrera B-N33N8W /20NENE Pad; IGS 111 wellLocation ID #: 311896Form 2A# 401314079API #: 05-067-09139

Construction stormwater BMPs for well pad (diversion trenches, straw wattles, and other spill stormwater control equipment) and access road (borrow ditch for sediment control) are in-place and these stormwater controls indicate no evidence of offsite migration of fluids or sediment; however, based on the recent onsite and inspection (7-27-17) conducted by COGCC, additional stormwater controls will be required for the existing well pad area and the tank containment area of this oil and gas location; location is in dry land farming; no evidence of leaks or spills at wellhead; tank has secondary containment - no evidence of leaks or spills; signage for tank and wellhead are adequate; CPW had no recommendations.