

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/03/2017

Submitted Date:

08/07/2017

Document Number:

677900288**FIELD INSPECTION FORM**
 Loc ID 312854 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 36200Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM COAddress: 3600 S. YOSEMITE ST - STE 900City: DENVER State: CO Zip: 80237-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Griggs, Mary		mgriggs@sierra-hamilton.com	
		sharonsotoole@gmail.com	
Edelen, Randy		r.edelen@grynberg.com	
Arthur, Denise		denise.arthur@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
		ecooper@sierra-hamilton.com	
Colby, Lou		lou.colby@state.co.us	
Neidel, Kris		kris.neidel@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
100600	PIT	CL			-	CHIVINGTON 1	EI
100601	PIT	CL			-	CHIVINGTON 1	EI
222617	WELL	SI	05/07/2013	OW	081-05709	CHIVINGTON 1	EI

General Comment:

On August 3, 2017 COGCC Environmental Staff (Alex Fischer), conducted an inspection of Grynberg Petroleum Company, (Grynberg) Location ID 312854, Pit Facility ID 100600, Remediation (REM) 8333. Jerry Hoberg (Moffat County Planning) was present. Weather was partially cloudy and temperatures about 70 degrees Fahrenheit at time of Inspection. REM 8333 had been an ongoing remediation since about April 2014 and was closed in June of 2017.

NOTE; CONTACT

Colby, Lou - Area (142) Reclamation Inspector
lou.colby@state.co.us
(970) 876-1969
(970) 989-4402 (cell)

Arthur, Denise - Reclamation Supervisor
denise.arthur@state.co.us
(303) 894-2100 x5195
(720) 630-6533 (cell)

Inspected Facilities									
Facility ID:	100600	Type:	PIT	API Number:	-	Status:	CL	Insp. Status:	EI
Facility ID:	100601	Type:	PIT	API Number:	-	Status:	CL	Insp. Status:	EI
Facility ID:	222617	Type:	WELL	API Number:	081-05709	Status:	SI	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail	Other	Fail			

Comment:
 • There appeared to have been a recent precipitation event, as debris flow (vegetation) was noted about 6-8 inches entangled in the fence coming on Location from the west and off of Location to the east.
 • Sediment had moved across and off of Location.
 • Erosion features were noted across Location.
 RANDY EDLIN AND MARY GRIGGS WERE CONTACTED ON 8/7/2017 REGARDING SEDIMENT DISCHARGE OFF OF LOCATION.

Corrective Action: 1002.f, Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 08/09/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On August 3, 2017 COGCC Environmental Staff (Alex Fischer), conducted an inspection of Grynberg Petroleum Company, (Grynberg) Location ID 312854, Pit Facility ID 100600, Remediation (REM) 8333. Jerry Hoberg (Moffat County Planning) was present. Weather was partially cloudy and temperatures about 70 degrees Fahrenheit at time of Inspection. REM 8333 had been an ongoing remediation since about April 2014 and was closed in June of 2017. The following is a summary:</p> <ul style="list-style-type: none"> • The Location is fenced, gated and secured. • There appeared to have been a recent precipitation event, as debris flow (vegetation) was noted about 6-8 inches entangled in the fence coming on Location from the west and off of Location to the east. • A low lying "pond" had standing water. • Sediment had moved across and off of Location. • Erosion features were noted across Location. <p>On August 7, 2017, Alex Fischer contacted Randy Edlin (Grynberg) to let him know about the sediment leaving Location. Mr. Edlin directed Mr. Fischer to the Receivership (Mary Griggs).</p> <p>On August 8, 2017, Alex Fischer contacted Mary Griggs to let her know about the sediment leaving Location and referred her to Denise Arthur and Lou Colby (CGOCC Reclamation).</p> <p>NOTE: CONTACT REGARDING THE STORMWATER ISSUES</p> <p>Colby, Lou - Area (142) Reclamation Inspector lou.colby@state.co.us (970) 876-1969 (970) 989-4402 (cell)</p> <p>Arthur, Denise - Reclamation Supervisor denise.arthur@state.co.us (303) 894-2100 x5195 (720) 630-6533 (cell)</p>	fischera	08/07/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677900290	INSP Summary 20170803 Grynber Chivington Inspection Location ID 321854 Photo log.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218860
677900291	INSP Summary 20170803 Grynberg Location ID 312854 Pit Facility 100600 REM 8333.pdf	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218861