

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2017

Submitted Date:

08/07/2017

Document Number:

679100120**FIELD INSPECTION FORM**
 Loc ID 320858 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Naomi Azulai		naomi.azulai@bp.com	

General Comment:Date of Inspection: 5-10-17Type of Inspection: Interim Reclamation, Containment, StormwaterLocation Name: Carmelita Gallegos A 1 Pad; Carmelita Gallegos A 1 and A 3 wellsLocation ID #: 320858Form 2A# 401156218API #: 05-007-06325

Permanent stormwater and containment BMPs for this well pad expansion and the original well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with rock check dams for sediment control) are in-place and these stormwater controls indicate no offsite migration of fluids or sediment; cut and fill slopes of the original well pad have been partially to mostly re-vegetated; a 12" to 15" earthen berm placed around well pad perimeter for containment of temporary drilling tanks and temporary frac tanks; straw and straw wattles placed beyond berms for surface soil erosion control; location is within a designated setback location; no evidence of fugitive dust or odors reaching nearby residence during drilling operations.