

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2017

Submitted Date:

08/01/2017

Document Number:

666803428

FIELD INSPECTION FORM

Loc ID 334695 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284937	WELL	PR	01/07/2007	GW	045-12212	CIRCLE B LAND 24B-35-692	PR
285171	WELL	PR	01/08/2007	GW	045-12384	CIRCLE B LAND 14A-35-692	PR
285172	WELL	PR	01/08/2007	GW	045-12385	CIRCLE B LAND 24D-35-692	PR
285175	WELL	PR	01/09/2007	GW	045-12383	CIRCLE B LAND 14C-35-692	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Horizontal Heated Separator	# 4				
Plunger Lift	# 4				
Emission Control Device	# 1				
Ancillary equipment	# 1	Chemical unit at wellhead			
Gas Meter Run	# 0				

Tanks and Birms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Birms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	OTHER	STEEL AST				
Comment:		Bradenhead hooked up to 80bbbs tank					
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity) 80bbbs							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	6	OTHER	STEEL AST		39.477822,-107.638113		
Comment:							
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity) 250bbbs							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:				Date:			
Venting:							
Yes/No	YES						
Comment:		Bradenhead valves open					
Corrective Action:				Date:			
Flaring:							
Type							
Comment:							
Corrective Action:				Date:			

Inspected Facilities									
Facility ID:	<u>284937</u>	Type:	<u>WELL</u>	API Number:	<u>045-12212</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>285171</u>	Type:	<u>WELL</u>	API Number:	<u>045-12384</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>285172</u>	Type:	<u>WELL</u>	API Number:	<u>045-12385</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>285175</u>	Type:	<u>WELL</u>	API Number:	<u>045-12383</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift, Bradenhead hooked up to 80bbbls tank</u>							Date:	
Corrective Action:								Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	In Process					
		Ditches	Pass			
Ditches	Pass					
		Culverts	Pass			
		Gravel	In Process			
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401361600	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4213654