

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2017

Submitted Date:

08/02/2017

Document Number:

674901828**FIELD INSPECTION FORM**Loc ID 444691 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Fischer, Reed	(303) 981-2921	Inspections@catamountep.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444690	WELL	PR	06/23/2016	LO	067-09972	Morales 34-6-7 1	EI

General Comment:

On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Morales 34-6-7 #1. For the most recent field inspection report for this facility, please refer to document #685301112.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to guard fencing for pump jack reads "Morales 34-6-6U #1", COGIS database lists the well name for API #05-067-09972 as the "Morales 34-6-7 #1".		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/26/2017
Type	TANK LABELS/PLACARDS		
Comment:	Free standing signs near ASTs.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Emergency contact information posted on well head and tank battery signs.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Natural gas powered.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLs	HEATED STEEL AST		37.214571,-107.538389	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Polystar lined containment berm.				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	444690	Type:	WELL	API Number:	067-09972	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			
Waddles	In Process					
Drains	Pass					
Ditches	Pass					
Berms	Pass					

Comment: [Wattles on south side of location, downstream of location drain, require maintenance.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC Morales 34-6-7 #1. For the most recent field inspection report for this facility, please refer to document #685301112. Signs at the well head and the tank battery list the well name as "Morales 34-6-6U #1" while the COGIS database lists the name as "Morales 34-6-7 #1". Wattles on south side of location, downstream of location drain, require maintenance.	hughesj	08/02/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401362928	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214745
674901829	Well sign information differs from COGIS database.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214729
674901830	Undercut and filled in BMPs.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214730
674901831	Tank battery with lined containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214731