

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/02/2017

Document Number:

674901835

FIELD INSPECTION FORM

Loc ID 325654 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 16 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215173	WELL	PR	12/21/1988	GW	067-06778	EVELYN PAYNE A 1	EI

General Comment:

On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Evelyn Payne A #1. For the most recent field inspection report for this facility, please refer to document #674901299.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	21 bbl. PBV has label and placard.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Lube oil container is labeled "Mobil Pegasus 1 Oil".		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on well head sign.		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	WELLHEAD	<= 1 bbl	
Comment:	Stained gravel around well head and Oil lift equipment.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>09/04/2017</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Stock panel fencing around PBV.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Stock panel fencing around well head and Oil lift equipment.		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:			Date:

Type: Progressive Cavity	# 1	
Comment: Stained soil near wellhead, equipment is wet.		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Telemetry.		
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Oil lift pump controller. Stained soil near equipment.		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.261369,-107.555048
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	21 bbl.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 215173 Type: WELL API Number: 067-06778 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	In Process	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: [Erosion along eastern edge of location.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Evelyn Payne A #1. For the most recent field inspection report for this facility, please refer to document #674901299.</p> <p>Corrective actions required by that inspection have either not been addressed or have reoccurred. Stained gravel near the Oil Lift equipment and well head were observed during this field inspection.</p> <p>Erosional channels were observed along the eastern edge of the location.</p>	hughesj	08/02/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401363137	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214867
674901836	Stained soil near well head, wet equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214862
674901837	Stained gravel near Oil Lift equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214863
674901838	Erosion along eastern edge of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4214864