

Inspection Photos
Location Name SP 431-14
API: 05-045-19704



Photo 1. BMP damaged or not maintained

Inspection Photos
Location Name SP 431-14
API: 05-045-19704



Photo 2. BMP damaged or not maintained

Inspection Photos
Location Name SP 431-14
API: 05-045-19704



Photo 3. Sediment migration from pad surface

Inspection Photos
Location Name SP 431-14
API: 05-045-19704




Photo 4. Sediment migration from pad surface

Inspection Photos
Location Name SP 431-14
API: 05-045-19704



Photo 5. Erosion on pad surface

Inspection Photos
Location Name SP 431-14
API: 05-045-19704



Photo 5. Cut slope not stabilized, debris and sediment moving onto pad

Inspection Photos
Location Name SP 431-14
API: 05-045-19704



Photo 5. Sediment migration along lease road.

