



Photo 1: View of the project area from the southwestern edge facing center.



Photo 2: View of the southern portion of the project area from the southwestern edge of the well pad facing eastward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of the southwestern portion of the project area from the southwestern edge of the well pad facing westward.



Photo 4: View of what appears to be oil and water in wellhead cellar.



Photo 5: View of oil stained soils adjacent to wellhead.



Photo 6: View of unmarked rig anchor in southern portion of well pad.



Photo 7: View of another unmarked rig anchor on the southern edge of the well pad.



Photo 8: View of what appears to be cement debris or cuttings in the southern portion of the interim reclamation area.



Photo 9: View of trash in the project area. Several of these water bottles are scattered around the project area.



Photo 10: Another view of trash within the project area.



Photo 11: View of unsecured trash bag within the project area.



Photo 12: View of Canada thistles (*Cirsium arvense*) within the project area.