

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2017

Submitted Date:

08/09/2017

Document Number:

680200081**FIELD INSPECTION FORM**

Loc ID 418429 Inspector Name: KELLERBY, SHAUN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
TEP, Energy		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>
Murray, Richard		g.richard.murray@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418441	WELL	PR	06/30/2013	GW	045-19700	Federal SP 341-14	PR
418445	WELL	TA	11/03/2014	SI	045-19704	Federal SP 431-14	TA
418449	WELL	PR	05/31/2013	GW	045-19708	Federal SP 432-14	PR
418455	WELL	PR	06/30/2013	GW	045-19714	Federal SP 342-14	PR

**General Comment:**

Form 4 sundry approved and submitted on 12/18/14 placing well in a TA status Doc # 400756061.

Form 6 Doc # 401302272 submitted on 7/27/17

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 418441 Type: WELL API Number: 045-19700 Status: PR Insp. Status: PR**Producing Well**Comment: On plunger lift

Corrective Action:

Date:

Facility ID: 418445 Type: WELL API Number: 045-19704 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment: Well has not been completed.

Corrective Action:

Date:

Facility ID: 418449 Type: WELL API Number: 045-19708 Status: PR Insp. Status: PR**Producing Well**Comment: On plunger lift

Corrective Action:

Date:

Facility ID: 418455 Type: WELL API Number: 045-19714 Status: PR Insp. Status: PR**Producing Well**Comment: On plunger lift

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Cogcc staff observed sediment migration during inspection. Cut slope of location has not been stabilized and debris and sediment is moving onto the pad. BMP need to be maintained on and around location. Sediment is migrating past BMP along the lease road. Location is included with each photo attached to inspection.

Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 09/11/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680200082	418445	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4221943</a>