



**Photo 1: View of the project area from the southwestern corner facing center.**



**Photo 2: View of the southern portion of the project area from the southwestern corner of the well pad facing southeastward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascoyprum smithii*), and smooth brome (*Bromus inermis*).**



**Photo 3: View of the western portion of the project area from the southwestern corner of the well pad facing northeastward.**



**Photo 4: View of unknown riser at approximately 37.093632, -107.726581 at the edge of the western portion of the project area.**



**Photo 5: View of what appears to be surface owner debris in the northeastern portion of the project area.**



**Photo 6: View of fence debris in the southern portion of the project area.**



**Photo 7: View of erosional channel in the northern portion of the project area needing stabilization measures.**