

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



Access road looking east, weeds need controlled



Access road heading west, weeds need controlled. Truck shown as reference to height

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



Battery sign looking east at production tanks



Tanks and heater treater from south side of tanks looking north

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



Unused/unmarked 3" riser on east side of north crude tank



Erosion at discharge run down on north side of battery

Inspection Photos

Location Name: Wagner 11-65 9-1H

API: 05-123-33345



Erosion at discharge run down on north side of battery



Unused/unmarked 3" riser on south side of ECD



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



West side of ECD and flare looking east



Weeds need to be controlled on location

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



West side of pump jack looking east



Stained soil at wellhead and pump jack skid

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



Propane tank on east side of pump jack with no labeling



Propane tank on east side of pump jack with no labeling

Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



North of production tanks looking east, recirculating pump



Trash on east side of production tanks

Inspection Photos

Location Name: Wagner 11-65 9-1H

API: 05-123-33345



Stained soil on northwest side of pump jack motor



Incorrect operator and emergency contact information on wellhead sign

Inspection Photos

Location Name: Wagner 11-65 9-1H

API: 05-123-33345



Erosion on lease road hill looking south



Lease road on hill washing out, sediment is carrying of road



Inspection Photos
Location Name: Wagner 11-65 9-1H
API: 05-123-33345



Lease road on hill erosion, hard hat used as reference