

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/04/2017

Document Number:

674901842

### FIELD INSPECTION FORM

Loc ID 306850 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
 Name of Operator: BP AMERICA PRODUCTION COMPANY  
 Address: 380 AIRPORT RD  
 City: DURANGO State: CO Zip: 81303

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269598	WELL	PR	08/22/2005	GW	067-08882	ALBRIGHT-TRIMBLE 2	EI

**General Comment:**

On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Albright Trimble #2. For the most recent field inspection report of this facility, please refer to document #674600440.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Free standing sign near PBV.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Stock panel fencing around all equipment on site.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1	
Comment:	Telemetry	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.254870,-107.538386
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 269598 Type: WELL API Number: 067-08882 Status: PR Insp. Status: EI

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: 

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
On August 1, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Albright Trimble #2. For the most recent field inspection report of this facility, please refer to document #674600440.	hughesj	08/04/2017

**Attached Documents**
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401365985	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217535">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217535</a>
674901843	Trimble Albright #2 location photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217531">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217531</a>
674901844	Trimble Albright #2 pump jack and well head.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217532">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217532</a>